



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D412-664-203

Job Sheet 194660



Part No: D412-664-203

Job Qty: 1 pcs

Part Name: Aft Crosstube - High



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 5/7/19

Job Tracking No:

Due Date: 3/15/19

Created By: Shannon Hadley

Type: Stock

Description: SIOP

Note: D412-664-243 REV F/ IIN-D212-664 REV.J IPP Rev:E 04.02.16 Reformat; Added D3189-1 K/DS IPP Rev:F
06-03-29 Remove Comments on Pick List JLM IPP Rev:G 06.12.08 per ECN 886 EC IPP Rev:H 07-04-30 As per
Rev D JLM IPP Rev:I 08-06-12 add comment in seq. 21 DD verified by:EC IPP rev J 11.04.21 DEO D412-664-
243-E-1 EC verified DD IPP REV:K 11.10.03 DEO D412-664-243-E-2 DD ver:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier	Sign-off
					Setup Hrs	Run Hrs		
110	Packaging 1 - Pick Kit	1 pcs		3/15/19	0.00	0.00	Packaging 1 - 1	
							Packaging 1 - 2	
							Packaging 1 - 3	
							Packaging 1 - 4	
							Packaging 1 - 5	
							Packaging 1 - 6	
							Packaging 1 - 7	
							Packaging 1 - 8	
							Packaging 1 - 9	
							Packaging 1 - 10	
							Packaging 1 - 11	
							Packaging 1 - 12	
							Packaging 1 - 13	
							Packaging 1 - 14	
							Packaging 1 - 15	
							Packaging 1 - 16	
							Packaging 1 - 17	
							Packaging 1 - 18	
							Packaging 1 - 19	
							Packaging 1 - 20	
							Packaging 1 - 21	
							Packaging 1 - 22	
							Packaging 1 - 23	
							Packaging 1 - 24	
							Packaging 1 - 25	
							Packaging 1 - 26	
							Packaging 1 - 27	
							Packaging 1 - 28	
							Packaging 1 - 29	

GP 19-05-09



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S178705



Part: D412-664-203

Job No: 194660

Serial No/Batch: S178705

Revision: F/J

Inspector:

Exp Date:

Instructions: TC STC SH01-9 Issue 3, FAA STC SR01298NY 09/01/08, EASA ST

					Packaging 1 - 30	
					Packaging 1 - 31	
					Packaging 1 - 32	
					Packaging 1 - 33	
					Packaging 1 - 34	
					Packaging 1 - 35	
					Packaging 1 - 36	
120	Crosstubes - Bend - 2 - B4B	1 pcs	3/15/19	0.00 5.26	Crosstubes - Bend - B4B	GP 19-05-09
130	QC 15	1 pcs	3/15/19	0.00 0.00	QC 15 - 12	
					QC 15 - 3	
					QC 15 - 47	
					QC 15 - 49	
					QC 15 - 58	
					QC 15 - 9	DAS
					QC 15 - 68	MAY 09 2019 68
140	Crosstubes - 2 - B4B	1 pcs	3/15/19	0.00 3.33	Crosstubes - 1 - B4B	9-89
					Crosstubes - 2 - B4B	
					Crosstubes - 3 - B4B	
					Crosstubes - 4 - B4B	
160	Crosstubes - 3 - B4B	1 pcs	3/15/19	0.00 1.03	Crosstubes - 1 - B4B	
					Crosstubes - 2 - B4B	
					Crosstubes - 3 - B4B	
					Crosstubes - 4 - B4B	
165	QC 7	1 pcs	3/15/19	0.00 0.00	QC 7 - 10	
					QC 7 - 13	
					QC 7 - 14	
					QC 7 - 15	
					QC 7 - 17	
					QC 7 - 18	
					QC 7 - 19	
					QC 7 - 2	
					QC 7 - 28	
					QC 7 - 3	
					QC 7 - 30	
					QC 7 - 34	
					QC 7 - 36	
					QC 7 - 37	
					QC 7 - 41	
					QC 7 - 47	
					QC 7 - 48	
					QC 7 - 51	
					QC 7 - 58	
					QC 7 - 59	
					QC 7 - 60	
					QC 7 - 9	DAS
					QC 7 - 68	MAY 13 2019 68
					QC 7 - 50	9-89
					QC 7 - 67	
					QC 7 - 40	
					QC 7 - 24	
					QC 7 - 43	
170	QC 5	1 pcs	3/15/19	0.00 0.00	QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
					QC 5 - 24	

				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	DAS MAY 13 2019 68 9-89
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
180	Outsource	1 pcs	3/15/19	SKY002-VC	5 KH 2019-05-17
190	Packaging 2-1 - Receive - B4B	1 pcs	3/15/19	0.00 0.00	Packaging 2 - 1 - B4B Packaging 2 - 2 - B4B Packaging 2 - 3 - B4B Packaging 2 - 5 - B4B Packaging 2 - 4 - B4B Packaging 2 - 6 - B4B Packaging 2 - 7 - B4B Packaging 2 - 8 - B4B Packaging 2 - 9 - B4B Packaging 2 - 10 - B4B Packaging 2 - 11 - B4B Packaging 2 - 12 - B4B Packaging 2 - 13 - B4B Packaging 2 - 14 - B4B Packaging 2 - 15 - B4B Packaging 2 - 16 - B4B Packaging 2 - 17 - B4B Packaging 2 - 18 - B4B Packaging 2 - 19 - B4B Packaging 2 - 20 - B4B Packaging 2 - 21 - B4B Packaging 2 - 22 - B4B Packaging 2 - 23 - B4B Packaging 2 - 24 - B4B Packaging 2 - 25 - B4B Packaging 2 - 26 - B4B Packaging 2 - 27 - B4B Packaging 2 - 28 - B4B Packaging 2 - 29 - B4B Packaging 2 - 30 - B4B Packaging 2 - 31 - B4B Packaging 2 - 32 - B4B Packaging 2 - 33 - B4B Packaging 2 - 34 - B4B Packaging 2 - 35 - B4B Packaging 2 - 36 - B4B
200	QC 5	1 pcs	3/15/19	0.00 0.00	QC 5 - 10 QC 5 - 12 QC 5 - 17 QC 5 - 18 QC 5 - 19 QC 5 - 22 QC 5 - 24 QC 5 - 3 QC 5 - 43 QC 5 - 49 QC 5 - 51

					QC 5 - 58		DAS
					QC 5 - 68	MAY 21 2019	68
					QC 5 - 9		9-89
					QC 5 - 50		
					QC 5 - 30		
					QC 5 - 40		
210	Spray Paint - 2 - B4B	1 pcs	3/15/19	0.00 1.47	Spray Paint - 1 - B4B		• AR 19-5-18
					Spray Paint - 2 - B4B		
					Spray Paint - 3 - B4B		
					Spray Paint - 4 - B4B		
					Spray Paint - MJ1 - B4B		
					Spray Paint - MJ2 - B4B		
					Spray Paint - MJ3 - B4B		
					Spray Paint - MJ4 - B4B		
220	QC 14	1 pcs	3/15/19	0.00 0.00	QC 14 - 15		
					QC 14 - 2		
					QC 14 - 34		
					QC 14 - 41		
					QC 14 - 51		
					QC 14 - 58		
					QC 14 - 59		
					QC 14 - 9		
					QC 14 - 68	MAY 21 2019	DAS 68
					QC 14 - 40		9-89
					QC 14 - 19		
					QC 14 - 43		
					QC 14 - 24		
230	Crosstubes - 4 - B4B	1 pcs	3/15/19	0.00 3.33	Crosstubes - 1 - B4B		
					Crosstubes - 2 - B4B		
					Crosstubes - 3 - B4B		
					Crosstubes - 4 - B4B		• AR 19-5-19
240	QC 5	1 pcs	3/15/19	0.00 0.00	QC 5 - 10		
					QC 5 - 12		
					QC 5 - 17		
					QC 5 - 18		
					QC 5 - 19		
					QC 5 - 22		
					QC 5 - 24		
					QC 5 - 3		
					QC 5 - 43		
					QC 5 - 49		
					QC 5 - 51		
					QC 5 - 58		
					QC 5 - 68	MAY 24 2019	DAS 68
					QC 5 - 9		9-89
					QC 5 - 50		
					QC 5 - 30		
					QC 5 - 40		
250	Packaging 1-1 - Pick Kit - B4B	1 pcs	3/15/19	0.00 0.00	Packaging 1 - 1 - B4B		
					Packaging 1 - 2 - B4B		
					Packaging 1 - 3 - B4B		
					Packaging 1 - 4 - B4B		
					Packaging 1 - 5 - B4B		
					Packaging 1 - 6 - B4B		
					Packaging 1 - 7 - B4B		
					Packaging 1 - 8 - B4B		
					Packaging 1 - 9 - B4B		
					Packaging 1 - 10 - B4B		
					Packaging 1 - 11 - B4B		

				Packaging 1 - 12 - B4B	
				Packaging 1 - 13 - B4B	
				Packaging 1 - 14 - B4B	
				Packaging 1 - 15 - B4B	
				Packaging 1 - 16 - B4B	
				Packaging 1 - 17 - B4B	
				Packaging 1 - 18 - B4B	
				Packaging 1 - 19 - B4B	
				Packaging 1 - 20 - B4B	
				Packaging 1 - 21 - B4B	
				Packaging 1 - 22 - B4B	
				Packaging 1 - 23 - B4B	
				Packaging 1 - 24 - B4B	
				Packaging 1 - 25 - B4B	
				Packaging 1 - 26 - B4B	
				Packaging 1 - 27 - B4B	
				Packaging 1 - 28 - B4B	
				Packaging 1 - 29 - B4B	
				Packaging 1 - 30 - B4B	
				Packaging 1 - 31 - B4B	
				Packaging 1 - 32 - B4B	
				Packaging 1 - 33 - B4B	
				Packaging 1 - 34 - B4B	
				Packaging 1 - 35 - B4B	
				Packaging 1 - 36 - B4B	
260 QC 4	1 pcs	3/15/19	0.00 0.00	QC 4 - 28	
				QC 4 - 58	
				QC 4 - 69	Me
				QC 4 - 9	
				QC 4 - 46	
				QC 4 - 68	
270 Packaging 3-1 - Stock - B4B	1 pcs	3/15/19	0.00 0.00	Packaging 3 - 1 - B4B	Me
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	

				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
275	DC - 1 - B4B	1 pcs	3/15/19	0.00 0.00	DC - 1 - B4B
					DC - 2 - B4B
280	QC 21 - FG	1 pcs	3/15/19	0.00 0.00	QC 21 - FG - 21
					QC 21 - FG - 70
					QC 21 - FG - 53

DAS 21 MAY 30 2019
9-89
DAS 21 MAY 30 2019
9-89

Part Op 110 - (Pick Kit)
 Descriptions: 120 - CNC Alpha 160 Bender) Bend tube as per Dwg D412-664-243 using CNC bender program 412-aft and Folio FT010
 130 - (QC15- Crosstube Dimensional Check)
 140 - 1-Drill pilot holes in tube as per Dwg D412-664-243 using drill Jig DT8550 & DT8551 and drill table DT8577 using #9 holes as per QSI 10 to install towers. 2-Ream hole to finish size in tube as per Dwg D412-664-243 using drill Jig DT8550 & DT8551. Check dimensions between holes, both sides on both cuffs, to ensure alignment with saddle holes. 3-SCRIBE PART # & BATCH # ACCORDING TO NOTE 6
 4- *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE*** Deburr & Inspect for surface damage. Repair damage within limits as per Dwg D412-664-243
 160 - (Crosstubes Chemical Conversion) ***IMMEDIATELY AFTER GRINDING***
 165 - (QC7-Inspect Chemical Conversion Coat)
 170 - (QC5- Inspect part completeness to step on W/O) INSPECT ENGRAVING AND BATCH #
 180 - *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE***
 190 - (Receive & Inspect for Damage & Mat'l Certs) *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE***
 200 - (QC5- Inspect part completeness to step on W/O) *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE***
 Inspect for damage & ensure results are as per Dwg D412-664-203
 210 - *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE*** **VERIFY BY BATCH # TO MATCH W/O
 1-Prime inside and outside crosstube as per QSI 005 4.2 AND DWG
 PRIMER: 5154137 START TIME: 2-Paint outside crosstube with White Imron as per DWG D412-664-243 and QSI 005 4.2 3- Apply clear coat after paint as per DWG clear 515467 Paint 5179047
 220 - (QC14- Inspect Spray Paint) Then, Wrap in plastic bag to protect from scratches
 230 - Assemble as per Dwg D412-664-203 1- Install center support using scoth-weld DP460 per QSI 015, as per DWG. note 13. Install supports clamps using as per Dwg D412-644-243. Install clamp with rubber cushion as per DWG. note 14. ***ENSURE CLAMPS ARE ON TOP OF CROSSTUBE SUPPORT*** Torque clamps on support to 80-100 IN-LBS AS PER DWG. EXP DATE: 2- **IF NOT ALREADY PRESENT ON CHAFFING SHEILD.** Apply a thin coat of proseal 890 per QSI 015 on inside concave surface of chafing shield and let cure per manufacturer's instructions. Install prosealed chafing shield onto crosstube by applying a thin coat of proseal 890 onto crosstube. Be sure to eliminate any air gaps. Install and torque clamps on chafing shield to 40-50 IN-LBS AS PER DWG. EXP DATE: AFTER FINISH CURE TIME 24H START CURE TIME: FINISH CURE TIME:
 240 - (QC5- Inspect part completeness to step on W/O) ***RE-CHECK TORCQUE ON CLAMP AFTER PROSEAL HAS CURED FOR 24HOURS AS PER DWG.***
 250 - (Pick Kit)
 260 - (QC4- 100% Inspect kits for completeness)
 270 - (Identify as per dwg & Stock Location:) Identify and pack for shipping as per PPP D412-664-203
 *****Ensure tube is not packaged if curing time is less than 12 hrs, see step 27 for application time & date ***** Time & date of packaging: Location: FG103
 275 - Photocopy bluefile and create labels as per PPP D412-664-203 CHG 010
 280 - (QC21- Final Inspection - Work Order Release) 1- *****LAY DOWN CORSTUBE ON TABLE AND PUT DT10302 PINS IN SADDLE HOLE FACING UP TO LOCATE CENTER OF CROSSTUBE***** Install center support using scoth-weld DP460 per QSI 015, as per DWG. note 13. Install supports clamps using as per Dwg D412-644-243. Install clamp with rubber cushion as per DWG. note 14. ***ENSURE CLAMPS ARE ON TOP OF CROSSTUBE SUPPORT*** Torque clamps on support to 80-100 IN-LBS AS PER DWG. 1- *****LAY DOWN CORSTUBE ON TABLE AND PUT DT10302 PINS IN SADDLE HOLE FACING UP, USE HOLE IN TAPE MESURE TO PUT IN PINS FOR LOCATING CENTER OF CROSSTUBE. ***** Install center support using scoth-weld DP460 per QSI 015, as per DWG. note 13. Install supports clamps using as per Dwg D412-644-243. Install clamp with rubber cushion as per DWG. note 14. ***ENSURE CLAMPS ARE ON TOP OF CROSSTUBE SUPPORT*** Torque clamps on support to 80-100 IN-LBS AS PER DWG.

SW
3152077
2xp 3/20
PS
5146134
Exp 10/19

009982

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D412-664-203TRN	Crosstube Turning Detail	1 pcs (1 ea)	110-Packaging 1 - Pick Kit	5145137
D2896-1	Support	1 pcs (1 ea)	230-Crosstubes - 4 - B4B	
D3189-1	Chaffing Shield	2 pcs (2 ea)	230-Crosstubes - 4 - B4B	
D3595-063-570	Rubber Cushion 0.63" Wide X 5.70" Long	2 pcs (2 ea)	230-Crosstubes - 4 - B4B	
MS21920-28	Clamp	4 Ea (4 ea)	230-Crosstubes - 4 - B4B	
MS21920-30	Clamp	2 Ea (2 ea)	230-Crosstubes - 4 - B4B	
AN6-40A	3/8-24 Bolt X 3" Long	4 Ea (4 ea)	250-Packaging 1-1 - Pick Kit - B4B	5171903x2
AN6-41A	Bolt	2 Ea (2 ea)	250-Packaging 1-1 - Pick Kit - B4B	5038736
MS21042L6	Nut	6 Ea (6 ea)	250-Packaging 1-1 - Pick Kit - B4B	5182058
NAS1149D0663J	Washer	18 Ea (18 ea)	250-Packaging 1-1 - Pick Kit - B4B	5135105

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
110-Packaging 1 - Pick Kit	D412-664-203TRN	1	4	0
230-Crosstubes - 4 - B4B	D2896-1 5053883	①	19	0
	D3189-1 5175238	②	23	0
	D3595-063-570 5056672	②	103	0
	MS21920-28 5162134	④	170	0
	MS21920-30 5005127	②	41	0
250-Packaging 1-1 - Pick Kit - B4B	AN6-40A	4	108	0
	AN6-41A	2	57	0
	MS21042L6	6	318	0
	NAS1149D0663J	18	1,212	0

Part Specifications

Specifications could not be found.

Plex 5/7/19 9:11 AM Dart.Hadley.Shannon

DART AEROSPACE LTD

Work Order: 194460

Description: Crosstube High Aft (412)


Part Number: D412-664-203

Inspection Dwg: D412-664-243

Rev: F

Page 1 of 1

Required Dimension	Min	Max
Height	24.12	24.62
1/2 Span	53.59	53.85
Angle	49	52
Total Span	107.18	107.70
Bending Passes	8	--
Crushing	--	7%



	Side A	Side B
Bending Passes		
Crushing	7.0%	6.6%
Comments		

QC15 Inspection	
Date	

Rev	Date	Change	Revised by	Approved
A	07.02.06	New Issue	KJ/JM	
B	07.05.08	Dimensions updated per Dwg rev. D	KJ/JLM	
C	10.02.02	Dwg Rev updated	KJ	
D	12.04.16	Added bending, crushing dimensions	KJ	
E	14.09.08	Max crushing % revised	KJ	

Item	Qty -243	Part Number	Description
1	X	D412-664-243	CROSSTUBE ASSEMBLY (412 HIGH AFT)
2	1	D6009-129	CROSSTUBE
3	2	D3595-063-570	RUBBER CUSHION
4	1	D2896-1	SUPPORT
5	2	D3189-1	CHAFING SHIELD
7	4	MS21920-28	CLAMP
8	2	MS21920-30	CLAMP (OR MS21920-32)
9	A/R	SCOTCH-WELD DP460	EPOXY ADHESIVE, 3M SCOTCH-WELD
10	A/R	PROSEAL 890 B-2	SEALANT

GENERAL NOTES:

- 1) MATERIAL: MANUFACTURED FROM D6009-129
FINISHED LENGTH = 124.100±0.020 (BEFORE BENDING)
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2
MASK UNDERSIDE OF CROSSTUBE AS SHOWN (ZN C8-2, HATCHED AREA)
PAINT OUTSIDE PER DART QSI 005 4.2
AFTER PAINTING, REMOVE MASKING AND APPLY MATTE CLEAR COAT
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED.
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX.
- 6) IDENTIFICATION: DART P/N "D412-664-243" AND B/N ON INSIDE OF CUFF PER QSI 044 6.4 (VIBRATING STYLUS)
- 7) WEIGHT: 47.0 lbs
- 8) PART IS SYMMETRIC ABOUT CENTERLINE.
- 9) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE. DO NOT GRIND TUBE AFTER SHOT PEEN.

TURNING

- 10) WHEN TRANSITIONING TO STOCK MAT'L, RUN CUTTER OFF PART. BLEND OUT EDGE LONGITUDINALLY. TRANSITION SHOULD BE SMOOTH.

BENDING

- 11) BEND PROGRESSIVELY WITH A MINIMUM OF 8 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 7% (BASED ON O.D.) IN LOWER HALF OF R30 BEND AND 6% (BASED ON O.D.) ON REMAINING TUBE.
- 12) LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038. TO BE PERFORMED AFTER FINAL POST-BEND GRINDING. ANY ADDITIONAL GRINDING REQUIRES ANOTHER LPI INSPECTION.

ASSEMBLY

- 13) INSTALL D2896-1 CENTER SUPPORT USING A 0.04" TO 0.07" THICK LAYER OF SCOTCH-WELD DP460 PER QSI 015.
- 14) INSTALL MS21920-30 CLAMPS (OR -32) WITH D3595-063-570 RUBBER CUSHIONS TO SECURE THE D2896-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE ON TOP SIDE OF CROSSTUBE.
- 15) APPLY A THIN COAT OF PROSEAL 890 ON INSIDE CONCAVE SURFACE OF D3189-1 CHAFING SHIELD AND LET CURE PER MANUFACTURER'S INSTRUCTIONS. INSTALL PROSEAL 890 ON INSIDE CONCAVE SURFACE OF D3189-1 CHAFING SHIELD ONTO CROSSTUBE BY APPLYING A THIN COAT OF PROSEAL 890 ONTO CROSSTUBE. BE SURE TO ELIMINATE ANY AIR GAPS.
- 16) TORQUE CLAMPS ON D2896-1 SUPPORT 80 TO 100 IN-LB. TORQUE CLAMPS ON D3189-1 CHAFING SHIELD 40 TO 50 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING. PRIOR TO PACKAGING, RE-CHECK TORQUE ON CLAMPS AFTER ADHESIVES HAVE CURED FOR 24 HOURS.

RELEASED
2014-05-26

F	NOTES RE-ORDERED, SCOTCH-WELD WAS MAGNOBOND (C8-1), ADD CLAMP RETORQUE (A8-1), REMOVE ABRASION STRIP, ADD INSPECTION WINDOW (C8-1), CHAFING SHIELD NOW 4.38 WIDE (C8-2), ADD 7% CRUSHING (B8-1), CHG BEND HEIGHT TOL. TO ±0.25 (C1-3), CHG CUFF TOL. (D2-4), CLAMPS FLIPPED TO PREVENT CHAFING (B7-2, B7-3), INCORP. DEO E-2/4	CP	14.04.01
E	REFORMAT/REVISE GENERAL NOTES; REORGANIZED VIEWS AND REFORMATTED DRAWING TO CURRENT STANDARDS; RELOCATED FLAG #6 PER PAR 08-046 (ZN A6-3); ADD TOLERANCE (ZN B6-3, C4-3, C8-3 & C5-3); MOVED TURNING DETAIL & UPDATED TOLERANCE TO SHEET 4.	RF	09.09.30
D	REMOVE D2732-058, CHANGE TO D3595-063-570	PH	07.03.09
C	REMOVE D2856-600-1087, ADD D2732-058 & MAGNOBOND 6398, MS21920-32 WAS MS21920-30	MB	06.10.27
B	ADD HOLES FOR COMPATABILITY WITH BHT/AA SKIDTUBES	PH	05.02.04
A	NEW ISSUE	PH	01.10.17
REV.	DESCRIPTION	BY	DATE
DESIGN			
DRAWN			
CHECKED			
MFG. APPR.			
APPROVED			
DE APPR.			
DATE	14.04.01		

DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWING NO. D412-664-243	REV. F SHEET 1 OF 4
TITLE CROSSTUBE ASSEMBLY (412 HI AFT)	SCALE NTS
COPYRIGHT © 2001 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED IN ANY MANNER WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

Entered: _____ Date: _____






WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					



RELEASED
2014-05-26

DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO. D412-664-243	REV. F
MFG. APPR.		TITLE	SHEET 2 OF 4
APPROVED		CROSSTUBE ASSEMBLY (412 HI AFT)	SCALE
DE APPR.			NTS
DATE	14.04.01	COPYRIGHT © 2001 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Entered: _____ Date: _____




WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____


Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					


8 7 6 5 4 3 2 1



D412-664-603
BENDING AND DRILLING DETAIL



C1-3 **VIEW D-D: CUFF DETAIL**
SCALE 4X



SECTION C-C D5-3
SCALE 4X

RELEASED
2014-05-26

DESIGN	<i>JP</i>	DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>DW</i>	DRAWING NO.	REV. F
MFG. APPR.	<i>MB</i>	D412-664-243	SHEET 3 OF 4
APPROVED	<i>MB</i>	TITLE	SCALE
DE APPR.	<i>MB</i>	CROSSTUBE ASSEMBLY (412 HI AFT)	NTS
DATE	14.04.01	COPYRIGHT © 2001 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR CONVEYED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD			

8 7 6 5 4 3 2 1

Entered: _____ Date: _____




WORK ORDER NON-CONFORMANCE / ROUTE UPDATE


NCR No. _____

Route update only ☐


Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					




D412-664-243TRN
TURNING DETAIL



DETAIL E:
CROSSTUBE CUFF
SCALE 5X D8-4



DETAIL G:
CUFF TRANSITION
SCALE 10X C2-4



DETAIL F:
TAPER RUN-OFF
NOT TO SCALE C4-4

RELEASED
2014-05-26

DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D412-664-243	SHEET 4 OF 4
APPROVED		TITLE	SCALE
DE APPR.		CROSSTUBE ASSEMBLY (412 HI AFT)	NTS
DATE	14.04.01	COPYRIGHT © 2001 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD			

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread ☐			
Other/Details:					



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

PURCHASE ORDER

POHB043464



Supplier: SKY002-VC
Skyservice
6120 Midfield Road
Mississauga
ON
L5P 1B1 Canada
Phone: 905-678-5636
Fax: 905-678-5841

Attention: Jenne, Heather

Ship To: 1270 Aberdeen Street
Hawkesbury
ON
K6A 1K7 Canada
Phone: 613-632-5200

PO No: POHB043464

PO Date: 5/15/19

Due Date: 5/17/19

**Purchase Order
Revision:**

Revision Date:

Ship-To Contact: Phone:

Via: Ground

Pynt Terms: Net 30

Freight Terms:

Special Comments:

Items

Line Item	Job	Part	Description	Status	Account	Due Date	Order Quantity	Received Quantity	Balance	Unit Price (CAD)	Extended Price
1	194661	D412-664-203	Aft Crosstube - High : TC STC SH01-9 Issue 3, FAA STC SR01298NY 09/01/08, EASA STC EASA.IM.R.S.01304 07/03/06, DGAC MEXICO STC IA- 316/2015 15/06/17 *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE***	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	194660		1x MAY 2 1 2019	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	194662		1x MAY 2 1 2019	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	194658		1x MAY 2 1 2019	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
Sub Total:							4	0	4		\$435.20

2	187571	D119-796-241	Aft Crosstube Installation Without Step (No Hardware) : TC STC SH14-45-Issue 1, FAA STC SR03504NY 15/01/28, EASA STC 10052022 Revision 1 15/02/13, DGCA INDIA LoA 07-09/2011-AED (Part) 15/07/16, BRAZIL STC 2015S07-16 15/07/30, CAAP PHILIPPINES LoA 16/05/11, CHINA VSTC0757 16/07/22, RUSSIA STC CT316-A119 16/08/11, DGAC INDONESIA STC SR025 18/02/19 *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE*** *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE***	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
---	--------	--------------	---	--------	---	---------	-------	-------	-------	--------------	----------

Plex 5/17/19 2:51 PM Dart.Guerin.Kimberley



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

PURCHASE ORDER

POHB043464



Items											
Line Item	Job	Part	Description	Status	Account	Due Date	Order Quantity	Received Quantity	Balance	Unit Price (CAD)	Extended Price
	194137		<i>ix</i> MAY 21 2019 <i>[Signature]</i>	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	194138		<i>ix</i> MAY 21 2019 <i>[Signature]</i>	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	194136		<i>ix</i> MAY 21 2019 <i>[Signature]</i>	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
Sub Total:							4	0	4		\$435.20
3	187563	D119-796-141	Fwd Crosstube Installation Without Step (No Hardware) : TC STC SH14-45-Issue 1, FAA STC SR03504NY 15/01/28, EASA STC 10052022 Revision 1 15/02/13, DGCA INDIA LoA 07-09/2011-AED (Part) 15/07/16, BRAZIL STC 2015S07-16 15/07/30, CAAP PHILIPPINES LoA 16/05/11, CHINA VSTC0757 16/07/22, RUSSIA STC CT316-A119 16/08/11, DGAC INDONESIA STC SR025 18/02/19 Outsource2 (Outsource process - NDT per QSI038 4.1) *** WEAR LATEX GLOVES WHEN HANDLING CROSSTUBE*** Liquid Penetrant Inspection as per QSI 038Or Issue P/O: _____ LPI as per ASTM 1417 Level 2 Attach copy of NDT results to work order	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
	187560		<i>ix</i> MAY 21 2019 <i>[Signature]</i>	Firmed	-	5/17/19	1 pcs	0 pcs	1 pcs	\$108.80/pcs	\$108.80
Sub Total:							2	0	2		\$217.60
Grand Total:										\$1,088.00	



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

PURCHASE ORDER

POHB043464



Order Notes

Procurement Quality Clauses

A005 right of entry
A012 chemical and physical test report
A016 personnel qualification
A017 raw material identification (as applicable)

A022 Apical Processing
A024 process certifications
A026 certification of material conformance

A041 quality management system
A042 dart notification by supplier
A043 retention of quality documents

A048 counterfeit parts avoidance, detection, mitigation and disposition program

A049 supplier awareness

Terms & Condition of Purchasing(Suppliers) and Procurement Quality Clauses are an integral part of our AS9100 requirements. To learn in detail, please visit www.dartaerospace.com for further explanation.

A handwritten signature in black ink, consisting of stylized, overlapping loops and lines.

Plex 5/17/19 2:51 PM Dart.Guerin.Kimberley

**skyservice****Work Order Traveler**
Sky Service F.B.O. Inc.

10105 Ryan Avenue, Dorval, Quebec, H9P 1A2

TCCA AMO 53-89 / EASA 145 7142 / BDA AMO 385

WO #: MWO40427	Customer: Dart Aerospace Ltd.	Dept: NDT YUL	Reference: POHB043464 ✓
Descr:	PN:	S/N:	Qty: 1
Make:	Model:	Reg:	A/C S/N:
TSN:	CSN:	TSO:	
Task: UNSCHEDULED			Sequence: 1

Work Required:**CARRY OUT NDT INSPECTION (LIQUID PENETRANT) ON 10 CROSSTUBES**

ITEM ID: D412-664-203 AFT CROSSTUBE - HIGH

1 - WORK ORDER ID#: 194660 ✓

2 - WORK ORDER ID#: 194661 ✓

3 - WORK ORDER ID#: 194662 ✓

4 - WORK ORDER ID#: 194658 ✓

ITEM ID: D119-796-241 AFT CROSSTUBE INTS. WITHOUT STEP.

5 - WORK ORDER ID#: 194138 ✓

6 - WORK ORDER ID#: 194136 ✓

7 - WORK ORDER ID#: 194137 ✓

8 - WORK ORDER ID#: 187571 ✓

ITEM ID: D119-796-141 FWD CROSSTUBE INTS. WITHOUT STEP

9 - WORK ORDER ID#: 187563 ✓

10 - WORK ORDER ID#: 187560 ✓

RECEIVED

MAY 21 2019

DART AEROSPACE LTD.

Action Taken:						Date:	Initial/Stamp:
LIQUID PENETRANT INSPECTION CARRIED OUT ON ITEMS LISTED ABOVE (ITEMS 1-10) AS PER ASTM1417M-16						MAY 15 2019	
NO CRACK FOUND							
PEN ZL-37, MPO23206, CLEANER SKC-S MPO15030, EMU. MPO15896, DEV. MPO23451, UV LIGHT M-20142							
Description	Location	P/N	Qty	Batch	S/N Off	S/N On	

I certified that the maintenance described above has been performed in accordance with the applicable standard of airworthiness.

Signature:	ACA/SCA Stamp 	Date:
Name: ANTONINO MARCHETTA		MAY 15 2019

5.0 PARTS LIST

5.1 HIGH GEAR CROSSTUBES

Item	QTY -101	QTY -201	QTY -203	Part Number	Description
	X			D212-664-101	CROSSTUBE INSTALLATION, 204/205/210/212/214/412, UH-1H, UH-1A/B/E/F/L/P, TH-1F/L, HH-1K HIGH FWD
		X		D212-664-201	CROSSTUBE INSTALLATION, 204/205/210/212/214, UH-1H, UH-1A/B/E/F/L/P, TH-1F/L, HH-1K HIGH AFT
			X	D412-664-203	CROSSTUBE INSTALLATION, 412 HIGH AFT
1	1			D212-664-141	CROSSTUBE ASSEMBLY, 204/205/210/212/214/412, UH-1H, UH-1A/B/E/F/L/P, TH-1F/L, HH-1K HIGH FWD
2		1		D212-664-241	CROSSTUBE ASSEMBLY, 204/205/210/212/214, UH-1H, UH-1A/B/E/F/L/P, TH-1F/L, HH-1K HIGH AFT
3			1	D412-664-243	CROSSTUBE ASSEMBLY, 412 HIGH AFT
10	2			* D2893-1	SUPPORT
11	4			* D3595-063-450	RUBBER CUSHION
12	4			* MS21920-25	CLAMP (OR MS21920-26)
13	4			AN6-35A	BOLT
14	4			AN6-36A	BOLT
15	6			MS21042L6	NUT (OR MS21042-6)
16	18			AN960JD616	WASHER
20		2		* D2940-1	SUPPORT
21		4		* D3595-063-530	RUBBER CUSHION
22		4		* MS21920-28	CLAMP (OR MS21920-30)
23		4		AN6-40A	BOLT
24		2		AN6-41A	BOLT
25		6		MS21042L6	NUT (OR MS21042-6)
26		18		AN960JD616	WASHER
30			1	* D2896-1	SUPPORT
32			2	* D3595-063-570	RUBBER CUSHION
33			4	* MS21920-28	CLAMP
34			2	* MS21920-30	CLAMP (OR MS21920-32)
35			4	AN6-40A	BOLT
36			2	AN6-41A	BOLT
37			6	MS21042L6	NUT (OR MS21042-6)
38			18	AN960JD616	WASHER
39			2	* D3189-1	CHAFING SHIELD
50	1	1		D3428-1	PLACARD

* REFERENCE ONLY. PARTS ARE INCLUDED IN D212-664-141/-241 OR D412-664-243 ASSEMBLIES ABOVE.

NOTE: KITS INCLUDE EXTRA HARDWARE FOR COMPATIBILITY WITH BOTH DART AND BELL/AAI SKIDTUBES.

PAGE 1 OF 1

Description: CROSSTUBE INSTALLATION, HIGH AFT

[illegible]

PAGE 1 OF 1

Description: CROSSTUBE INSTALLATION, HIGH AFT

[illegible]